

TEST REPORT -3634

Assured Testing Services

224 River Road Ridgway, PA 15853 USA
 Ph: (814) 773-3224 Fax (814) 773-3225
 Email: danielleschatz@assuredtestingservices.com



TESTING CERT# 2012.01

CLIENT

CLIENT

BILL TO: AFI001	OurSupplier ID
Alloy Fasteners, Inc	
15 Amflex Drive	
Cranston RI 02921	
USA	Supplier Code
Attn:	Ph:

SHIP TO: AFI001	OurSupplier ID
Alloy Fasteners, Inc	
15 Amflex Drive	
Cranston RI 02921	
USA	Supplier Code
Attn:	Ph:

Test Report No: 3634 **Test Entry Date:** Tuesday, April 15, 2008 **Contact Name:**

Test Remarks: *Revised Test Report 3634A: Added "+" to lot name.*
Revised Test Report 3634B: Changed 1000+ to 1500+ and "E" and "F"

Client Information		Part Test Information						
PART NUMBER	PO NUMBE	INDATE	OUTDATE	TESTCNT	RETCNT	HOURS	CYCLES	
LOT NUMBER	WO-REL#	TEST SPECIFICATION NAME			REQ	COMP	REQ	COMP
RECEIVED DATE	OURJOBID	TEST PROCEDURE NAME						
PART DESCRIPTION		TEST STATUS						

Samples	TBD	15-Apr-08	17-Jun-08	5		1512	
AlloChrome 1500+, Lot E	TBD	UNDEFINED					
29-May-08	3016	Salt Spray Testing Per ASTM B117-07a					
<i>Parts ID #1 through 5 had no red rust present at 1512 hrs of exposure.</i>							
Samples	TBD	15-Apr-08	17-Jun-08	5		1512	
Allo Chrome 1500+, Lot F	TBD	UNDEFINED					
29-May-08	3016	Salt Spray Testing Per ASTM B117-07a					
<i>Parts ID #1 through 5 had no red rust present at 1512 hrs of exposure.</i>							

Danielle Schatz

Revision# 1.3 Date 2/19/08

End Of Report

General Manager